


General Procedures - Main User Interface

Open Control Center	CTRL+SHIFT+C
Open Graphics Administration	CTRL+SHIFT+G
Open Process Designer: create new process	CTRL+SHIFT+P
Open Process Designer: open existing process	CTRL+SHIFT+O
Display the online Help	F1

Process Designer

Add instance of last selected operation	ALT+click viewport
Create new process	CTRL+N
Delete	DELETE
Export process	CTRL+E
Import process	CTRL+I
Open existing process	CTRL+O
Redo last undone command	CTRL+Y
Run process	F5
Save process	CTRL+S
Select all	CTRL+A
Select/clear selection	CTRL+click operation in viewport
Step through process	F10
Undo last command	CTRL+Z